


N.Venkata Ramana Rao  
Structural Engineer.

  
**vee aar**  
Architects And Engineers  
A.S.Rao Nagar, Kapra, Hyd.

**RC NO: 1194/HYD/2024**


**STRUCTURAL STABILITY CERTIFICATE**


1. I have inspected the **N P S SCHOOL**  
( Run by Sri chaitanya bharathi educational society) situated in  
SURVEY NO 238 & 246 PART  
PUPPALAGUDA VILLAGE, GANDIPET  
MANDAL, RANGAREDDY DIST District,  
and found that the Building has Cellar,  
Stilt and Five upper Floors i.e., Total Six  
Floors above ground level, and the Height  
of the Building under consideration is  
18.00 meters.




The **N P S SCHOOL** Represented by: Correspondent:  
**Putti Sreenivasa Rao.**

2. I have thoroughly inspected the said Building and found  
that no adverse indications about the structural weakness or  
impairment in the Building.
3. I therefore hereby certify that the said building is Structurally  
safe and Structurally Sound as on date for running  
**the School for the Academic year -2025-2026**

  
**Principal**  
**NPS SCHOOL**  
Puppalguda(V) Gandipet(M)  
Rangareddy(Dist)

  
**N. Venkata Ramana Rao**  
Lic. No. 19/Str. Engineer/TP10/GHMC/2024-29  
Plot No 2, G Block, A.S Rao Nagar, Kapra, Hyd

  
**Manager**  
**NPS SCHOOL**  
Puppalguda(V) Gandipet(M)  
Rangareddy(Dist)

Signature of The Structural Engineer  
(N.VENKATA RAMANA RAO)

Date - 29 Dec-2024